



Single Survey

Clair Cottage Murrayfield Castletown KW14 8TY





survey report on:

Customer	Kenneth & Lynda Chalmers
Customer Address	
Date of Inspection	29 th August 2023
Prepared by	Keith J Bowman BSc MRICS Registered Valuer





SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report onto Lender specific proforma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspected date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.¹

If the Surveyors have had a previous business relationship within the last two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking this box.

 \boxtimes

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions of assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct





Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential Surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;

any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;

- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained with the Report and the generic Mortgage Valuation Report².

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, is the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.





1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property the Surveyor concludes that the property is exempt under Part 3 of the Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property"" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the Report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of the Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.





PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words: visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the Property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats, it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and Effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The Report on the location, style and condition of the Property will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion are not significant. If certain minor matters are mentioned, it should not be interpreted that the Property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the Property.

- 2.3.1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the Property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1:</u> No immediate action or repair is needed.

WARNING: If left unattended even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the Property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.





2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion of both the market value of the property and the reinstatement cost as defined below:

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of Market Value the Surveyor can also make various standard assumptions covering, for example, vacant possession, tenure and other legal considerations, contamination and hazardous materials, the condition of un-inspected parts, the right to use mains services, and the exclusion of curtains, carpets, etc. from the valuation. In the case of flats, the following further assumptions are made that:

- there are rights of access and exit over all communal roadways, corridors, stairways, etc. and to use communal grounds, parking areas and other facilities;
- there are no particularly troublesome or unusual legal restrictions;
- there is no current dispute between the occupiers of the flats or any outstanding claims or losses and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumptions or any found not to apply are reported.

"Reinstatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.





1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a detached 1 and 2 storey dwelling house with integral garage.
Accommodation	Ground Floor: Entrance vestibule, inner hallway, lounge, kitchen/dining room, one bedroom, shower room and utility room.
	First Floor: Landing, two bedrooms (one currently used as dressing room) and bathroom.
Gross internal floor area (m²)	151.
Neighbourhood and location	The subjects are located on the periphery of the village of Castletown and afford ready access to the local facilities in the village.
Age	Built circa 1981.
Weather	Overcast with rain.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	One rendered chimney stack is provided.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The main roof is timber framed, sarked and finished with concrete interlocking tiles. Various trap hatches are provided to coombed areas and to trap hatch in the main landing roof space ceiling area. There is a further trap hatch within the garage area.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Of PVC manufacture.
Main walls	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.
	Appear of cavity block construction with dry dash render finish externally. We note these have been cavity wall insulated in the past.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open.
	Windows and doors to the property are of double glazed UPVC design with some being upgraded in the more recent past. External joinery is largely overclad with UPVC finishes.
External decorations	Visually inspected.
External decorations	Visually inspected. None.





	None.
Communal areas	Circulation areas visually inspected.
	None.
Garages and permanent outbuildings	Visually inspected.
outbuildings	Integral block built garage is provided in keeping with that of the main property under pitched and tiled roof. A further store cupboard is also provided off the garage area. Two timber shed are provided in the garden grounds. These fall out with the Home Report remit.
Outside areas and boundaries	Visually inspected.
	Areas of garden ground are provided to the front and side with tarred drive. Areas are bounded by a variety of walls and fencing.
Ceilings	Visually inspected from floor level.
	Of plaster and plasterboard design with some areas of timber cladding.
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Of plaster and plasterboard design.
Floors including sub-floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. Physical access to the sub-floor area may be taken if the Surveyor deems it safe and reasonable to do so and subject to a minimum clearance of 1m between the floor joists and the solum as determined from the access hatch.
	Flooring throughout is of suspended timber and concrete construction.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved. Kitchen units were visually inspected excluding appliances.
	Internal joinery fittings are consistent with a property of this age and style with some having been upgraded in the more recent past. The kitchen is provided with modern fitted units and work surfaces.
Chimney breasts and	Visually inspected. No testing of the flues or fittings was carried out.
fireplaces	A decorative fire surround is provided in the living room with electric fire over and chimney capped and vented.
Internal decorations	Visually inspected.
	Internal decoration comprises of paint, wallpaper and varnish finishes consistent with the property's age and style.
Cellars	Visually inspected where there was safe and purpose-built access.
	N/A
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off the Surveyor will report this in the Report and will not turn them on.
	Mains supply. Electric switch gear and meter located in the understairs cupboard area.





Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off the Surveyor will report this in the report and will not turn them on. Bulk LPG cylinders provided to the side area of garden ground.
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.
	Mains supply. The plumbing installation appears to be of PVC and copper pipework. Bathroom and shower room fittings are of a modern standard pattern.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.
	Heating is by way of combi LPG boiler located within the attic space coomb. This supplies water filled radiators and hot water to the subjects.
Drainage	Drainage covers etc were not lifted. Neither drains nor drainage systems were tested.
	Connected we assume to the public sewer.
Fire, smoke and burglar alarms	Visually inspected. No tests whatsoever were carried out to the system or appliances.
	Various battery operated smoke detection was noted.
	Fire Safety legislation effective from February 2022 requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat detecting alarm must be installed in every kitchen area and all smoke and heat alarms must be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance, eg. central heating boiler, open fire, wood burning stove, etc a carbon monoxide detector is also required. The purchaser(s) should appraise themselves of the requirements of this legislation and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection

Access throughout the property was restricted due to floor coverings, furnishings and belongings. Stored items (particularly in cupboards) have not been moved. No access was gained to any sub floor areas. Roof space inspection was limited to head and shoulders to the main trap hatches and it was noted that coombed roof space areas are largely boarded and panelled out.

All properties built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask a specialist to undertake an appropriate test.

We have not made checks to ascertain whether the property lies within a Radon area. Further advice should be sought from the National Radiological Protection Board.

We have not been able to ascertain whether safety glass has been installed to glazing where required.


No checks have been made with regard to flood risk.

We have not carried out an inspection for Japanese Knotweed or other invasive plant species and unless otherwise stated for the purposes of this report we have assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. The identification of Japanese Knotweed or other invasive plant species should be made by a Specialist Contractor.





Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.





2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacements are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Struct	ural movement
Repair Category	1
Notes	Evidence of minor movement and hairline cracking was noted which appears typical for a property of its age and type. On the basis of a single visit this is considered to be of longstanding.

Dampi	ness, rot and infestation
Repair Category	1
Notes	No evidence of dampness, rot or infestation was noted to any areas inspected.

Chimn	ey stacks
Repair Category	1
Notes	Chimney stacks show signs of normal weathering. We note the chimney has been capped and vented.

Roofin	g including roof space
Repair Category	1
Notes	Roof coverings show signs of normal weathering. It would appear that roof coverings are largely original to the property's construction and show signs of minor undulation typical of a building of this age and type.

Rainw	ater fittings
Repair Category	1
Notes	Rainwater goods appear to have been updated in the more recent past.
	It should be noted that a full assessment of the rainwater fittings can only be made during heavy rainfall.

Main v	walls
Repair Category	1
Notes	No significant defects noted. We understand the property has been cavity wall insulated in the past and evidence of this was noted.





	- 46		
	-61		i
-	_		
	_		
		10.	

Windows, external doors and joinery

Repair Category	1
Notes	Windows and doors show signs of normal weathering. One of the side panels to the entrance door was noted to have failed. We note some of the windows are of an older pattern and could be considered for upgrading to personal preference in future. We further note the doorway to the garage cupboard is boarded over. We assume replacement windows and/or doors have been installed in line with relevant regulations and guidelines.
	We would point out that we have not tested all windows and doors.

	-		
- 1			
	~		
		533	

External decorations

acceptance of the control of the con	
Repair Category	N/A
Notes	

Conser	vatories/porches
Repair Category	N/A
Notes	

Communal areas	
Repair Category	N/A
Notes	

Garages and permanent outbuildings	
Repair Category	1
Notes	The garage shows signs of normal wear and tear in keeping with that of the main property. No significant defects were noted at the time of inspection. We assume adequate fire protection is provided from the garage to adjoining parts of the property.

Outside	e areas and boundaries
Repair Category	1
Notes	Outside areas will require ongoing maintenance in the future. We note the small pond area, such a feature can be a risk to children.

Ceiling	s
Repair Category	1
Notes	No significant defects noted.







Internal walls

Repair Category	1
Notes	No significant defects noted.



Floors including sub-floors

Repair Category	1
Notes	No significant defects noted. Minor unevenness to some areas of first floor flooring were noted. This is typical of the buildings age and type.
	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.



Internal joinery and kitchen fittings

Repair Category	1
Notes	No significant defects noted. We note the internal joinery and kitchen fittings have been updated in the more recent past.



Chimney breasts and fireplaces

Repair Category	1
Notes	No significant defects noted. It appears the chimney has been capped and vented in the past. Currently disused with electric fire over.



Internal decorations

Repair Category	1
Notes	No significant defects noted.



Cellars

Repair Category	N/A
Notes	



Electricity

Repair Category	1
Notes Electrical system appears of modern standard pattern. No recent testing certification noted.	
	The Institution of Engineering and Technology recommends that inspection and testing is undertaken at least every 10 years and on change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with present IET regulations.







Gas

Repair Category	1
Notes	We assume the gas installation has been installed in line with relevant standards of the supplier.

Water	, plumbing and bathroom fittings
Repair Category	1
Notes	Fittings appear to have been upgraded to modern pattern in the more recent past. No significant defects noted.
	Ongoing checks should be made to plumbing fitments and sealants. Failure of seals can result in dampness and decay to adjoining/underlying areas.

Heati	ng and hot water
Repair Category	1
Notes	No significant defects noted.
	We assume the heating and hot water appliances have been installed and maintained in line with the manufacturer's guidelines. We further assume that service records can be made available as appropriate.

Draina	age
Repair Category	1
Notes	No significant defects noted.





Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

	Structural movement	1
	Dampness, rot and infestation	1
	Chimney stacks	1
	Roofing including roof space	1
	Rainwater fittings	1
	Main walls	1
A	Windows, external doors and joinery	1
Co	External decorations	N/A
	Conservatories/porches	N/A
	Communal areas	N/A
	Garages and permanent outbuildings	1
	Outside areas and boundaries	1
	Ceilings	1
	Internal walls	1
	Floors including sub-floors	1
	Internal joinery and kitchen fittings	1
W	Chimney breasts and fireplaces	1
	Internal decorations	1
	Cellars	N/A
A	Electricity	1
0	Gas	1
F	Water, plumbing and bathroom fittings	1
	Heating and hot water	1
F	Drainage	1

Repair Categories

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacements are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.





3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property</u>: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres</u>: For this purpose, 'unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes - parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1	Which floor(s) is the living accommodation on?	Ground & First
2	Are there three steps or fewer to a main entrance door of the property?	Yes
3	Is there a lift to the main entrance door of the property?	No
4	Are all door openings greater than 750mm?	No
5	Is there a toilet on the same level as the living room and kitchen?	Yes
6	Is there a toilet on the same level as the bedroom?	Yes
7	Are all rooms on the same level with no internal steps or stairs?	No
8	Is the unrestricted parking within 25 metres of an entrance door to the building?	Yes





4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

We assume a clear Property Enquiry Certificate shall be provided in due course and that the property has a clear Title. We further assume that any necessary statutory consents for the property in its current state are in place. If any works did require consent, then it has been assumed they meet the standards required by the Building Regulations or are exempt.

The Solicitor must also ensure that any prospective purchaser fully understands the nature, criteria and basis of a Home Report and in particular what a Home Report is and what it is not (an exhaustive Condition Report) and this should be done before any prospective purchaser makes an offer for this property based on the content of this report. If the Solicitor or purchaser requires any clarification in relation to this, they must contact the surveyor or familiarise themselves with the nature and criteria of this type of report.

It should be checked/confirmed that the tenure is absolute ownership and that there are no unduly onerous conditions or restrictive servitudes contained in the Title.

Advice should be sought with regard to the exact extent of ground pertaining to the subjects.

Where defects or repairs have been identified within this Home Report, regardless of whether reported as category 1, 2 or 3 (please read category definitions), it is always best practice to obtain detailed competitive estimates from reputable contractors or specialists prior to entering into any legally binding contract.

We assume there is a right of access to the property at the frontage and it is on a fair and equitable basis.

Estimated re-instatement cost for insurance purposes

£375,000

This figure is an opinion of an appropriate sum for which the property and garage should be insured against total destruction on a reinstatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussion with your insurers is advised. The figure should be reviewed annually and in the light of any future alterations or additions.

Valuation and market comments

The market value of the property as described in this report is £235,000 (Two Hundred and Thirty Five Thousand Pounds).

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, Title restrictions or servitude rights.

The property is of a type for which there tends to be a reasonable demand. With the property market having been more buoyant in the more recent past following Covid restrictions, a number of properties are selling at figures in excess of the Home Report value. It is unclear how long these market conditions and trends will continue.

Report Author:	Keith J Bowman BSc MRICS Registered Valuer
Firm:	Torrance Partnership LLP
Address:	165 High Street Invergordon Ross-shire IV18 0AL
Electronically signed by:	Keith J Bowman BSc MRICS Registered Valuer





Date of report:	29 th August 2023



Mortgage Valuation Report



Property Address:	Clair Cottage, Murravfie	ld, Castletown KW14 8TY	Ref No: 25418	
Seller's Name(s):	Kenneth & Lynda Chalm	•		
Date of Inspection:	29 th August 2023			
Property Details				
Property Type	House 🛛	Detached 🖂	If Flat/Maisonette Purpose Built	
!	Bungalow 🗌	Semi Detached	Converted	
1	Flat 🗌	Mid Terrace	Floor of subject property	
1	//aisonette	End Terrace	No of floors in block	
,		*Specify under General Comments	No of Flats in block	
Type of Construction	*Specify under General	Comments)	Traditional ×Non Tradition	al 🗌
<u>Tenure</u>				
Absolute Owner	Leasehold	☐ Age 42 ye	ears approximately	
Accommodation - (s	pecify number of roon	<u>ns)</u>		
Living Rooms 1	Bedrooms 3	Kitchens 1 Bath	rooms 2 WCs 0 Other 1	
			(Specify in Ge Remarks)	
Gross Floor Area (exc	luding garages & outbui	ildings) Interi	nal <u>151</u> m² External <u>173</u> m	2
Garage(s) / Outbuildir	gs 3	Parki	ing Space <u>Yes</u> Garden Yes ⊠ N	lo 🗌
Residential Element -	greater than 40% Yes [⊠ No □		
Construction				
Walls Brick	☐ Stone ☐ Cond	crete Timber-fra	med Other (specify in General Remarks) X
				, —
Roof Tile	⊠ Slate □ Aspł	halt 🗌 Felt	Other (specify in General Remarks	_
	<u> </u>	halt Felt	Other (specify in General Remarks	_
Subsidence, Settlem	ent and Landslip			_
Subsidence, Settlem Has the property suffe	ent and Landslip red structural movemen		Yes ⊠ No) <u> </u>
Subsidence, Settlem Has the property suffe If yes, is this recent or	ent and Landslip red structural movemen progressive?	nt?	Yes ⊠ No Yes □ No	_
Subsidence, Settler Has the property suffer If yes, is this recent of Is there evidence, his	ent and Landslip red structural movemen progressive? ory or reason to anticipa		Yes ⊠ No Yes □ No) <u> </u>
Subsidence, Settlem Has the property suffe If yes, is this recent or Is there evidence, his the immediate vicinity	ent and Landslip red structural movemen progressive? ory or reason to anticipa	nt? ate subsidence, heave,	Yes ⊠ No Yes □ No landslip or flood in Yes □ No	
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the ab	ent and Landslip red structural movemen progressive? ory or reason to anticipa ? ove, please provide deta	nt? ate subsidence, heave, ails in General Remarks	Yes ⊠ No Yes □ No landslip or flood in Yes □ No s.	
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the absence (Based on vis	ent and Landslip red structural movement progressive? ory or reason to anticipate? ove, please provide deta ual inspection only. If any	nt? ate subsidence, heave, ails in General Remarks	Yes ⊠ No Yes □ No landslip or flood in Yes □ No	
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the ab	ent and Landslip red structural movement progressive? ory or reason to anticipate? ove, please provide deta ual inspection only. If any	nt? ate subsidence, heave, ails in General Remarks services appear to be non	Yes ⊠ No Yes □ No landslip or flood in Yes □ No s.	
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the ab Services (Based on vis the supply in General Re	ent and Landslip red structural movement progressive? ory or reason to anticipate? ove, please provide deta ual inspection only. If any marks)	ate subsidence, heave, ails in General Remarks services appear to be non	Yes ⊠ No Yes □ No landslip or flood in Yes □ No S.	i) iii
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the ab Services (Based on vis the supply in General Re Drainage Mains Gas Mains	ent and Landslip red structural movement progressive? ory or reason to anticipal cove, please provide deta ual inspection only. If any marks) Private None	ate subsidence, heave, lails in General Remarks services appear to be non le Water	Yes ⊠ No Yes □ No landslip or flood in Yes □ No s. I-mains, please comment on the type and loca Mains ⊠ Private □ None	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent of Is there evidence, his the immediate vicinity If Yes to any of the ab Services (Based on visithe supply in General Report of the supply in General Repo	ent and Landslip red structural movement progressive? ory or reason to anticipal cove, please provide deta ual inspection only. If any marks) Private None	ate subsidence, heave, ails in General Remarks services appear to be non at a large water at a large lectricity	Yes No Yes No Yes No Iandslip or flood in Yes No No S. I-mains, please comment on the type and loca Mains Private None Mains Private None	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent of Is there evidence, his the immediate vicinity If Yes to any of the ab Services (Based on vist the supply in General Red Drainage Mains Gas Mains Central Heating	ent and Landslip red structural movement progressive? ory or reason to anticipal ove, please provide deta ual inspection only. If any marks) Private None Private None Yes Parti	ate subsidence, heave, ails in General Remarks services appear to be non Water Electricity al None	Yes ☐ No Yes ☐ No Iandslip or flood in Yes ☐ No S. In-mains, please comment on the type and loca Mains ☐ Private ☐ None Mains ☐ Private ☐ None Brief Description LPG boiler to water filled radiators	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the absolute supply in General Report of the Supply in Ge	ent and Landslip red structural movement progressive? ory or reason to anticipal ove, please provide deta ual inspection only. If any marks) Private None Private None Yes Parti	ate subsidence, heave, ails in General Remarks services appear to be non a	Yes No Yes No Yes No No Iandslip or flood in Yes No S. In-mains, please comment on the type and loca Mains Private None Mains Private None Mains Private None Mains Private None Mains Mains Private None Mains Mains Mains None Mains Mai	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the absolute supply in General Report of the supply in Ge	ent and Landslip red structural movement progressive? ory or reason to anticipal ove, please provide deta ual inspection only. If any marks) Private None Private None Yes Parti	ate subsidence, heave, ails in General Remarks services appear to be non Water Electricity al None	Yes No Yes No Yes No No Ilandslip or flood in Yes No S. In-mains, please comment on the type and loca Mains Private None Mains Private None Brief Description LPG boiler to water filled radiators ty Mixed residential/commercial Remote village	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the absolute supply in General Report of the supply in Ge	ent and Landslip red structural movement progressive? ove, please provide deta ual inspection only. If any marks) Private None Private None Yes Particular	ate subsidence, heave, ails in General Remarks services appear to be noned Water Electricity al None Residential within town/cit Commuter village	Yes No Yes No Yes No No Iandslip or flood in Yes No S. In-mains, please comment on the type and loca Mains Private None Mains Private None Mains Private None Mains Private None Mains Mains Private None Mains Mains Mains None Mains Mai	tion of
Subsidence, Settlem Has the property suffer If yes, is this recent or Is there evidence, his the immediate vicinity If Yes to any of the absolute supply in General Report of the supply in Ge	ent and Landslip red structural movement progressive? ory or reason to anticipal? ove, please provide deta ual inspection only. If any marks) Private None Private None Yes Participal idal Suburb	ate subsidence, heave, ails in General Remarks services appear to be noned Water Electricity al None Residential within town/cit Commuter village	Yes No Yes No Yes No No Ilandslip or flood in Yes No S. In-mains, please comment on the type and loca Mains Private None Mains Private None Brief Description LPG boiler to water filled radiators ty Mixed residential/commercial Remote village	tion of



Mortgage Valuation Report



Planning issues Has the property been extended / converted / altered? If yes, please comment in General Remarks	Yes		No	\boxtimes
General Remarks				
The subjects comprise a detached 1 and 2 storey dwelling house on the periphery of Castletown and aff	ords ready	access to	o local	facilities.
The property is noted to be in fair condition for its age and type having undergone various home impring the past. Minor points noted could be attended to during routine maintenance and home improvem				on works
Other rooms: utility room.				
Other construction: cavity concrete block.				
Essential Repairs				
None.				
Estimated cost of essential repairs £ Retention recommended Yes No	\boxtimes	Amoun	t £	
Comment on Mortgageability				
The subjects are suitable for mortgage loan terms.				
Valuations (Assuming Vacant Possession)				
Market value in present condition £235,	000			
Market value on completion of essential repairs £				
Insurance Reinstatement value £375,	000			
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)				
Is a Reinspection necessary?		No 🛛		





Energy Report



Energy Performance Certificate (EPC)

Dwellings

Scotland

CLAIR COTTAGE, MURRAYFIELD, CASTLETOWN, THURSO, KW14 8TY

Dwelling type:Detached houseDate of assessment:29 August 2023Date of certificate:30 August 2023

Total floor area: 151 m²

Primary Energy Indicator: 232 kWh/m²/year

Reference number: 6317-3128-4000-0201-6226 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst


Main heating and fuel: Boiler and radiators, LPG

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£9,960	See your recommendations
Over 3 years you could save*	£1,956	report for more information

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band E (42)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (57)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Room-in-roof insulation	£1,500 - £2,700	£591.00
2 Floor insulation (suspended floor)	£800 - £1,200	£747.00
3 Floor insulation (solid floor)	£4,000 - £6,000	£243.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity	★★★★ ☆	★★★★ ☆
Roof	Pitched, 250 mm loft insulation Roof room(s), insulated Roof room(s), ceiling insulated	**** **** ***	**** **** ***
Floor	Suspended, no insulation (assumed) Solid, no insulation (assumed)	_ _	_ _
Windows	Fully double glazed	***	★★★☆☆
Main heating	Boiler and radiators, LPG	***	★★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	****	★★★ ☆
Secondary heating	Room heaters, electric	_	_
Hot water	From main system	***	★★★ ☆
Lighting	Low energy lighting in 67% of fixed outlets	****	★★★★ ☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 48 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 7.3 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Latinated energy costs for this nome			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£8,463 over 3 years	£6,915 over 3 years	
Hot water	£723 over 3 years	£507 over 3 years	You could
Lighting	£774 over 3 years	£582 over 3 years	save £1,956
	Totals £9,960	£8,004	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

Estimated energy costs for this home

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

December ded massages		Indicative cost Typical saving		Rating after improvement		
Re	commended measures	Indicative cost per year		Energy	Environment	
1	Room-in-roof insulation	£1,500 - £2,700	£197	E 45	D 60	
2	Floor insulation (suspended floor)	£800 - £1,200	£249	E 50	D 64	
3	Floor insulation (solid floor)	£4,000 - £6,000	£81	E 52	D 65	
4	Low energy lighting for all fixed outlets	£25	£53	E 52	D 66	
5	Solar water heating	£4,000 - £6,000	£72	E 54	D 67	
6	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£598	D 61	C 73	

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

4 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

5 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

6 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	21,287	(223)	N/A	N/A
Water heating (kWh per year)	2,321			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Keith Bowman Assessor membership number: EES/008304

Company name/trading name: Torrance Partnership LLP

Address: 165 High Street Ross-shire

Invergordon IV18 0AL

Phone number: 01349 853151

Email address: admin@torrance-partnership.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

CLAIR COTTAGE, MURRAYFIELD, CASTLETOWN, THURSO, KW14 8TY 30 August 2023 RRN: 6317-3128-4000-0201-6226 Recommendations Report

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Seller(s) Lynda And Kenneth Chalmers Property Address Clair Cottage Murrayfield Castletown, Thurso KW14 8TY

Note for sellers

- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Q1: Length of Ownership)		
How long have you own	ed the property?		8/10
Q2: Council Tax			
Which council tax band i	s your property in?(Please Select)		D
Q3: Parking			
Garage	✓	Allocated Parking Space	*
Driveway	✓	Shared Parking	*
On Street	×	Resident Permit	*
Metered Parking	×		
Other (Please Specify)			
Q4: Conservation Area			
Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?			No
Q5: Listed Building			
Is your property a Listed Building or contained within one(that is a building recognised and approved as being or special architectural or historical interest)			No

Created On: 29/08/2023 Page 1 of 7 Pages

Q6: Alterations/Additions/Extensions	
a(i)	
During your time in the property, have you carried out a structural alteration, additions or extensions(for example, provision of an extra bath\shower room, toilet, or bedroom)?	No
Please describe the changes you made	N/A
a(ii)	
Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	No
If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	N/A
b(i)	
Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes
b(ii)	
Were the replacements the same shape and type as the ones your replaced?	No
b(iii)	
Did the work involve any changes to the window or door openings?	No
b(iiii)	
Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed)	5 UPVC windows replaced and double doors to kitchen reinstated between 2015 & 2021

Please give any guarantees which you received for this work to you solicitor or estate agent.

Created On: 29/08/2023 Page 2 of 7 Pages

Q7: Central Heating	
a(i)	
Is there a central heating system in your property?	Yes
(Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and bathroom).	
a(ii)	
What kind of central heating is there? (Example: gas-fired, solid fuel, electric storage heating, gas warm air).	gas-fired
a(iii)	
When was your central heating system system or partial heating system installed?	April 2015
a(iiii)	
Do you have a maintenance contract for the central heating system?	No
Please give details of the company with which you have a maintenance contract?	N/A
a(iiiii)	
When was your maintenance agreement last renewed? please provide month and year	N/A
Q8: Energy Performance Certificate	
Does your property have an Energy Performance Certificate which is less than 10 years old?	No
Q9: Issues that may have affected your property	
a(i)	
Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	No
is the damage the subject of any outstanding insurance claim?	N/A
b(i)	
Are you aware of the existence of asbestos in your property	No
Please give Details?	N/A

Created On: 29/08/2023 Page 3 of 7 Pages

Q10: Services

a(i)

Please tick which services are connected to your property and give details of the supplier

r loade tiek which dervices are confidence to your prop	orty and give details or the sap	эрны
	Connected	Supplier
Gas or Liquid Petroleum	✓	Calor
Water mains or private water supply	✓	Scottish Water
Electricity	✓	OVO Energy
Mains Drainage	✓	Scottish Water
Telephone	✓	ВТ
Cable TV or Satellite	*	N/A
BroadBand	✓	ВТ
b(i)		
Is there a septic tank at the property?		No
b(ii)		
Do you have appropriate consents for the discharge fr	rom your septic tank?	N/A
b(iii)		
Do you have a maintenance contract for your septic to	ank?	N/A
Please give Details?		N/A

Created On: 29/08/2023 Page 4 of 7 Pages

Q11: Responsibilities for shared OR Common Areas

a(i)

Are you aware of any responsibility to contribute to the cost of anything used jointly, such as No the repair of a shared drive, private road, boundary, or garden area? Please give details? N/A b(i) Is there a responsibility to contribute to repair and maintenance of the roof, common No stairwell or other common areas? Please give details? N/A c(i) Has there been any major repair or replacement of any part of the roof during the time you No have owned the property? Do you have the right to walk over any of your neighbours' property - for example to put out

your rubbish bin or to maintain your boundaries?

No

Please give details?

N/A

e(i)

As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundary?

No

Please give details?

N/A

f(i)

As far as you are aware, is there a public right of way across your any part of your property? (public right of way is a way over which the public las a right to pass, whether or not the land is privatly owned).

No

Please give details?

N/A

Created On: 29/08/2023 Page 5 of 7 Pages

Q12: Charges associated with your property	
a(i)	
Is there a factor or property manager for your property?	No
Please provide the name and address, and give details of any deposits held and approximate charges:	N/A
b(i)	
Is there a common buildings insurance policy?	No
Is the cost of insurance included in your monthly/annual factor's charges?	N/A
c(i)	
Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	N/A
Q13: Specialist Works	
a(i)	
As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property	No
Please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	N/A
b(i)	
As far as you are aware has any preventative work for dry rot, wet rot, or damp ever been carried out on your property?	No
Please give details:	N/A
c(i)	
Do you have guarantees relating to this work?	N/A
you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as ossible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate gent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown ne original estimate.	
Guarantees are held by:	N/A

Created On: 29/08/2023 Page 6 of 7 Pages

Agreed

V

Signature(s)

Q14: Guarantees									
a									
Are there any guarantees	nere any guarantees or warranties for any of the following:								
Electric Work	No	Roofing	No						
Central Heating	No	National House Building Council (NHBC)	No						
Damp Course	No	Any other work or installations?	Yes						
b									
Please give any details of the work or installations to which the guarantee(s) relate(s) new windows/doors									
С									
Are there any outstanding	No								
Please give details:	N/A								
Q15: Boundaries									
As far as you are aware, Years?	has any bo	oundary of your property been moved in the last 10	No						
please give any details.	N/A								
Q16: Notices that affect your property									
In the past three years ha	n the past three years have you ever received a notice:								
a(i)									
Advising that the owner of	owner of a neighbouring property has made a planning application?								
b(i)									
That affects your property	y in some o	other way? No							
c(i)									
That requires you to do a	iny mainter	nance, repairs or improvements to your property?	No						
if you have answered yes to any a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.									
Declaration									
Declaration by the seller(s) / or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.									

Created On: 29/08/2023 Page 7 of 7 Pages

Kenneth Chalmers & Lynda Chalmers